UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,301,357 B2

Page 1 of 1

APPLICATION NO.: 10/538785

DATED

: November 27, 2007

INVENTOR(S)

: Dai Shinozaki et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In claim 6, column 7, lines 19-22, "tester, circuit, the drivers being connected to the respective pairs of probe pins to apply the drivers applying a voltage, which causes a fritting phenomenon to the respective electrodes," should read --tester, the drivers applying a voltage, which causes a fritting phenomenon, to the respective electrodes,--.

Signed and Sealed this

Fifteenth Day of April, 2008

JON W. DUDAS Director of the United States Patent and Trademark Office